Division of Oil, Gas, & Mining Mining Report 01/24/94 MINE ID: S0190031 MINE NAME: CISCO SPRINGS #1 OPERATOR: JONES, MIKE CONTACT: MIKE JONES ADDRESS: 1951 MILL CREEK DR MOAB UT 84532 PHONE: (801)259-8511 Surface Owner: STATE BLM #: Mineral Owner: STATE Lease #: Sec Town Range Qtr-Qtr-Qtrl Qtr-Qtrl Qtrl Qtr-Qtr-Qtr2 Qtr-Qtr2 Qtr2 16 20.0S 23.ŎE Permit Status: APP Mine Type [(S)urface, (U)nderground]: S Mine Status (PRO, ACT, SUS, RET): ACT Acreage: Minerals Mined ΑU TENTATIVE APPROVAL FINAL APPROVAL LAST INSPECTED DATE RECEIVED DATE DATE 04/07/93 04/05/93 BOND TYPE: BOND AMOUNT: ANNUAL REPORT YEAR: 93 YTD Total DATE ISSUED: DATE ISSUED: NONCOMP NOTICES: 0 DATE RESOLVED: DATE RESOLVED: VIOLATIONS: 0 0

REVISIONS: 0 0 DATE REC'D: DATE APPROVED: AMENDMENTS: 0 DATE REC'D: DATE APPROVED:

COMMENTS:

MECHANICAL FILTERING PROCEDURE TO PROCESS ORE. SLURRY IS PUMPED FROM CISCO WASH INTO A BUILDING ALREADY ON SITE. AFTER PROCESSING, WATER IS SETTLED IN SMALL POND THEN RETURNED TO THE WASH. OPERATOR WAS TOLD TO CONTACT DWQ CONCERNING THE SLURRY, TAILINGS POND & DISCHARGE. ALSO TOLD TO CONTACT WATER RIGHTS IN PRICE TO SEE IF PERMIT IS NEEDED TO PUMP WATER FROM CISCO WASH. 1993 REPORT STATED THAT TESTING OF MACHINERY & ORE SAMPLING IS ONLY THING BEING DONE.